


004666280

67212 U.S. PTO
08/799400
02/12/97



08794400-021297

FIG. 2




FIG. 3





FIG. 4



08799400-001207

FIG. 5A




FIG. 5B




FIG. 6A






FIG. 6B



62120-00466280

FIG. 7



004666280

67212 U.S. PTO
08/799400
02/12/97

FIG. 8






FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13A




FIG. 13B




FIG. 13C




FIG. 14





FIG. 15



08799400-021297

FIG. 16A




FIG. 16B






FIG. 17A




FIG. 17B




FIG. 17C




FIG. 18A




FIG. 18B




FIG. 18C




FIG. 18D




FIG. 19A




FIG. 19B




FIG. 19C




FIG. 20




FIG. 21A




FIG. 21B




FIG. 21C




FIG. 22A




FIG. 22B




FIG. 22C




FIG. 22D





FIG. 22E



08799400-021297

FIG. 23A




FIG. 23B




FIG. 23C




FIG. 23D





FIG. 23E



08799400-00466280

FIG. 24A




FIG. 24B




FIG. 24C




FIG. 24D





FIG. 24E



08799400-00466480

FIG. 25A




FIG. 25B




FIG. 25C




FIG. 25D




FIG. 25E




FIG. 26A




FIG. 26B




FIG. 26C




FIG. 26D




FIG. 26E




FIG. 26F




FIG. 26G




FIG. 26H




FIG. 26I





FIG. 27



08799400-021297

FIG. 28A




FIG. 28B




FIG. 28C




FIG. 29A




FIG. 29B




FIG. 29C




FIG. 29D





FIG. 29E



08799400-021297

FIG. 30A




FIG. 30B




FIG. 30C




FIG. 30D





FIG. 30E



08799400-00466280



FIG. 31A




FIG. 31B




FIG. 31C




FIG. 31D




FIG. 31E






FIG. 32A




FIG. 32B




FIG. 32C




FIG. 32D




FIG. 32E




FIG. 33A




FIG. 33B




FIG. 33C




FIG. 33D




FIG. 33E





FIG. 34



08799400-021297

FIG. 35A






FIG. 35B



08799400.021297


A perspective view of the front portion of the device. It shows a curved front plate 60 supported by a front plate support member 61. A front plate locking member 62 is positioned at the bottom of the front plate. Other labels include 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100.

FIG. 37



67212 U.S. PTO
08/799400
02/12/97

FIG. 38



08799400-001297

FIG. 39




FIG. 40A





FIG. 40B



08799400.001997

FIG. 41A




FIG. 41B

